PHOTOS OF EXISTING RETAINING WALL ALONG ROUTE 11/15



South end of route 0011 retaining wall – looking North



Middle section of retaining wall – looking south and showing a utility pole adjacent to the wall



Drainage Pipe through wall near the middle section of the wall



Photo showing area of wall that is leaning

The plumb bob is attached to the surface of the wall at the top and the gap at the bottom is measured.