

FOR AN EXPLANATION OF BASE BIDS, SEE SECTION 010300 OF THE SPECIFICATIONS

.1 PROPOSER: Wohlsen Construction Company

Base Bid #1:

Lump Sum Offer: Thirteen million five-hundred fifty-five thousand Dollars and zero Cents
(Written)

\$ 13,555,000 .00
(Figures)

Base Bid #2:

Lump Sum Offer: Thirteen million five-hundred seventy thousand Dollars and zero Cents
(Written)

\$ 13,570,000 .00
(Figures)

Base Bid #3:

Lump Sum Offer: Thirteen million five-hundred seventy thousand Dollars and zero Cents
(Written)

\$ 13,570,000 .00
(Figures)

Base Bid #4:

Lump Sum Offer: Thirteen million five-hundred seventy thousand Dollars and zero Cents
(Written)

\$ 13,570,000 .00
(Figures)

SCHEDULE OF UNIT PRICES

Project: Capitol Complex Central Plant - Building Renovations, Chiller System Replacement

Project Number: DGS C-0948-0090 Phase 3

For an explanation of unit prices see Section 010250 'Unit Prices in Lump Sum Contracts' and any addendum that modifies Section 010250.

The unit prices are for adjusting the quantities of work listed below. In addition to the quantities identified in the Contract Documents, the Schedule of Unit Prices in Section 010250 lists any additional quantities to be included in the lump sum bid(s). Only one Unit Price is entered which will apply to both the 'add' and the 'deduct' adjustments for actual quantity.

Schedule of Unit Prices - General Construction (.1) Contract			
ITEM NO.	DESCRIPTION	UNIT OF MEASUREMENT	UNIT PRICE
1	Concrete Spall Repair for Columns and Walls	Square Foot	\$ 466
2	Concrete Spall Repair for Beams	Square Foot	\$ 480
3	Concrete Spall Repair for Slabs	Square Foot	\$ 306
4	Concrete Crack Repair for Columns and Walls	Linear Foot	\$ 126
5	Concrete Crack Repair for Beams	Linear Foot	\$ 135
6	Concrete Crack Repair for Slabs	Linear Foot	\$ 135
7	Steel Corrosion Repair	Linear Foot	\$ 213
8	Over-Excavation	Cubic Yard	\$ 132