



NORTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
1	K & B Logistics (accident)	US 322	The release associated with the accident was identified as having impacted soils. Confirmatory soil samples indicated that all compounds were below the SHS.	Cut, fill, roadway	NFA
2	Former Boalsburg Exxon 92608	US 322 and SR 45	The site was identified on the AUL and LUST databases. The AUL restricts the use of shallow groundwater for potable water supply or agricultural purposes. Previous uses included a gas station (State Gas and Oil Company) and a concrete fuel island in 1970.	None	NFAATT
	Boalsburg Car Company	334 Boal Avenue	The site appeared to operate as an automotive repair facility and used car lot with the potential for storage of hazardous chemicals and the potential of unreported releases.		
3	Automotive repair garage and used car lot	400 Boal Avenue	Groundwater monitoring wells were located on the western portion of the site. The site appeared to operate as an automotive repair garage and used car lot with the potential for storage of hazardous chemicals and the potential of unreported releases.	None	NFAATT
4	Happy Valley Refreshment/Car Wash	420 Boal Avenue	The potential for UST(s) associated with the car wash exists. Previous uses are unknown.	None	NFAATT
5	Wash World Car Wash	426 Boal Avenue	The potential for UST(s) associated with the car wash exists. Previous uses are unknown.	None	NFAATT



NORTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
6	Shawley Port-a-Potty and Tanks	618 Earlystown Road	A large garage and tanker truck storage/parking area was observed and there is the potential for storage of hazardous chemicals and the potential of unreported releases.	Cut, fill and RROW along the western portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
8	Bolus Freight Systems Inc. (diesel release)	US 322 and SR 45	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. Confirmatory soil samples indicated that all compounds were below the SHS.	Cut, fill and roadway	NFA
9	Prima Express Inc. (accident)	US 322 and SR 45	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. Contamination may still be present.	Cut, fill and roadway	Initiate Phase I ESA and possibly Phase II/III ESA
10	Paradise Datacom Inc. / Boalsburg Plant Locus Inc.	1012 East Boal Avenue	The site was identified on the AIRS databases and as an Air Emissions Plant. The facility manufactures radio and television broadcasting and wireless communication equipment. The site was identified on the FINDS, ECHO, PFAS ECHO, US AIRS, and RCRA NonGen / NLR databases. The site was identified as a historic generator. The potential for storage of hazardous chemicals and the potential for unreported releases exists.	None	NFAATT



NORTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
11	Exelis Inc./Blatek Inc.	176 Technology Drive	<p>The site was identified on the ECHO, RCRA-SQG, FINDS, and PFAS ECHO databases and waste types included lead, and TCE.</p> <p>The site was identified as a concrete block factory in 1970.</p> <p>The site was observed to be a large commercial machine shop and has the potential for storage of hazardous chemicals</p>	Cut, fill, roadway, stormwater basin and RROW along the northern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
	Sound Technology Inc.	171 Technology Drive	<p>The site was identified on the RCRA NonGen / NLR, MANIFEST, FINDS, and ECHO databases; as well as a Captive Hazardous Waste Facility that is inactive and in compliance.</p>		
12	PennDOT Maintenance Yard	1255 Boal Avenue	<p>The site was observed to be a maintenance storage yard with an AST and has the potential for storage of hazardous chemicals and the potential for unreported releases.</p>	<p>Cut, fill, roadway, and RROW along the southern portion of the site; portion of a stormwater basin on the southwestern corner of the site</p>	Initiate Phase I ESA and possibly Phase II/III ESA
13	Harris Township Maintenance Facility	325 Discovery Drive	<p>ASTs and a maintenance garage were observed on the site with the potential for storage of hazardous chemicals and the potential of unreported releases.</p>	<p>Cut, fill, roadway and RROW along the northern portion of the site</p>	Initiate Phase I ESA and possibly Phase II/III ESA
14	Brick and Stone Supply	409 Discovery Drive	<p>The site was occupied by a masonry contractor with the potential for storage of hazardous chemicals and the potential for unreported releases. The previous site uses are unknown.</p>	<p>Cut, fill, RROW along the northern portion of the site</p>	Initiate Phase I ESA and possibly Phase II/III ESA

NORTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
15	Energycap, Inc.	360 Discovery Drive	A large commercial structure was observed on the site with the potential for storage of hazardous chemicals and the potential for unreported releases. Previous uses are unknown.	None	NFAATT
16	DTC Logistics Inc. (accident)	US 322	The release associated with the accident was identified as having impacted soils and was active and not in compliance due to lack of paperwork documenting compliance.	Cut, fill and roadway	Initiate Phase I ESA and possibly Phase II/III ESA
17	Tait Farm	179 Tait Road	The site was observed to be a tree farm with the potential for herbicide and pesticide application.	Cut and RROW along the northern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
18	Kuhn Farm	2112 Boal Avenue	The site was observed to be a tree farm with the potential for herbicide and pesticide application.	Cut, fill, roadway, and RROW along the northeastern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
19	Oelbermann Farm	North side of Boal Avenue	The site was identified as having impacted soils and was listed as inactive and in compliance. The former tanks were not located in an area with proposed construction.	Cut, fill, roadway and stormwater basins in the central portion of the site	NFAATT
25	1 Cycle Center Harley Davidson No. 1 Cycle Center Harley Davidson Inc.	107 Yearicks Boulevard	The site was identified on the FINDS and ECHO databases, and on the PA DEP eMapPA website as an Envirofacts facility. The site was identified on the RCRA-SQG database. The business appeared to be a closed Harley Davidson dealer with the potential for previous storage of hazardous chemicals, and the site was listed for sale.	None	NFAATT



NORTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
27	322 Self-Storage	107 Yearicks Boulevard	The site was identified on the ECHO database pertaining to stormwater construction. The site was developed as a commercial property and previous uses are unknown.	None	NFAATT
29	Iron Horse Rods and Custom	2011 General Potter Highway	The site was identified on the PA DEP ESA Search Tool website as a Captive Hazardous Waste Facility and was observed to be a classic car and motorcycle sales business with the potential for storage of hazardous chemicals and the potential for unreported releases.	None	NFAATT
30	Best Line Power Sports / Indian Motorcycle	2031 General Potter Highway	The site was observed to be a motorcycle and ATV sales and repair facility with the potential for storage of hazardous chemicals and the potential for unreported releases.	None	NFAATT
31	JRs Quality Tile and Hardware	2041 General Potter Highway	The site was a commercial property with the potential for storage of hazardous chemicals and the potential for unreported releases as well as unknown previous uses.	None	NFAATT
32	Walker and Walker Equipment	2065 General Potter Highway	The site was an agricultural and construction equipment rental business with the potential for storage of hazardous chemicals and the potential for unreported releases.	None	NFAATT
	Auto Accessories of America		The site was identified on the PA DEP eMapPA and PA DEP ESA Search Tool websites as a Captive Hazardous Waste Facility.		
	Spring Creek Paving and Construction	Wagner Road	The site was identified on the PA DEP eMapPA website under the Inactive Storage Tanks database.		



NORTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
38	Tussey Mountain Gunsmithing	162 Wagner Road	The site was operating as a commercial gunsmithing operation with the potential for storage of hazardous chemicals and the potential for unreported releases.	None	NFAATT
39	Gas Pumps associated with a farm	242 Wagner Road	A gas pump was observed indicating the potential for UST(s) with petroleum products or hazardous chemicals and the potential for unreported releases.	None	NFAATT
40	Neff Farm	Off General Potter Highway	The site was identified on the SWF/LF database as a municipal waste operation.	None	NFAATT
43	Buried Tanker Cars	Near 112 Neff Road	Two large tanker cars were observed partially buried in a hillside. Contents, if any, are unknown and there is a potential for unreported releases.	None	NFAATT
46	Renninger Lumber Truck Spill - Charles Rishel Residence	2413 General Potter Highway	The site was identified as having impacted soils, and remediation was performed using the SHS. A potential filling station was identified in 1941.	None	NFAATT
47	Pets Come First	2451 General Potter Highway	The site was identified as a former filling station in 1941 and has the potential for former USTs and use of petroleum products and hazardous chemicals, as well as unreported releases.	None	NFAATT
48	Cowhers Auto Body	RD Box 272A / 114 Cider Press Road	The site was identified on the RCRA-SQG database and previous uses indicated automotive related operations. The use of petroleum products and hazardous chemicals, as well as unreported releases exists.	None	NFAATT



NORTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
49	RD Greenland and Son Masonry (release)	2606 General Potter Highway	A heating oil release to the surface from an AST was reported as well as an associated water contamination complaint.	Cut, fill, roadway, and RROW	Initiate Phase I ESA and possibly Phase II/III ESA
50	Wolfs Furniture Enterprises (accident)	Route 144 / US 322 near 2606 General Potter Highway	The release associated with the accident was identified as having impacted soils, and remediation was performed under the SHS.	Cut and fill along the southern side of the US 322	NFA
52	PTH Express (accident)	US 322 Westbound	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. The PA DEP reported this case was closed.	Cut along the southern side of US 322	NFA
53	Cole Transportation	103 Skyview Drive	The site was identified as having one 10,000-gallon diesel fuel tank. The site was a bus depot with automotive garages with the potential for storage of hazardous chemicals and the potential for unreported releases.	Cut, fill, roadway and RROW	Initiate Phase I ESA and possibly Phase II/III ESA
54	Bingman Lumber (accident)	Skyview Drive	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. The PA DEP reported this case was closed.	Cut, fill and roadway along north and south sides of US 322	NFA
55	322 Potters Mills APR Project, PennDOT Engineering District 2-0	Potters Mills	The site was identified as having impacted groundwater, and the potential for pyritic rock being exposed. A filling station was identified in this area in 1941 and 1962.	Cut, fill, roadway and stormwater basin	Initiate Phase I ESA and possibly Phase II/III ESA



CENTRAL ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
1	K & B Logistics (accident)	US 322	The release associated with the accident was identified as having impacted soils. Confirmatory soil samples indicated that all compounds were below the SHS.	Cut, fill, roadway	NFA
2	Former Boalsburg Exxon 92608	US 322 and SR 45	The site was identified on the AUL and LUST databases. The AUL restricts the use of shallow groundwater for potable water supply or agricultural purposes. Previous uses included a gas station (State Gas and Oil Company) and a concrete fuel island in 1970.	None	NFAATT
	Boalsburg Car Company	334 Boal Avenue	The site appeared to operate as an automotive repair facility and used car lot with the potential for storage of hazardous chemicals and the potential of unreported releases.		
3	Automotive repair garage and used car lot	400 Boal Avenue	Groundwater monitoring wells were located on the western portion of the site. The site appeared to operate as an automotive repair garage and used car lot with the potential for storage of hazardous chemicals and the potential of unreported releases.	None	NFAATT
4	Happy Valley Refreshment/Car Wash	420 Boal Avenue	The potential for UST(s) associated with the car wash exists. Previous uses are unknown.	None	NFAATT
5	Wash World Car Wash	426 Boal Avenue	The potential for UST(s) associated with the car wash exists. Previous uses are unknown.	None	NFAATT



CENTRAL ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
6	Shawley Port-a-Potty and Tanks	618 Earlystown Road	A large garage and tanker truck storage/parking area was observed and there is the potential for storage of hazardous chemicals and the potential of unreported releases.	Cut, fill and RROW along the western portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
8	Bolus Freight Systems Inc. (diesel release)	US 322 and SR 45	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. Confirmatory soil samples indicated that all compounds were below the SHS.	Cut, fill and roadway	NFA
9	Prima Express Inc. (accident)	US 322 and SR 45	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. Contamination may still be present.	Cut, fill and roadway	Initiate Phase I ESA and possibly Phase II/III ESA
10	Paradise Datacom Inc. / Boalsburg Plant Locus Inc.	1012 East Boal Avenue	The site was identified on the AIRS databases and as an Air Emissions Plant. The facility manufactures radio and television broadcasting and wireless communication equipment. The site was identified on the FINDS, ECHO, PFAS ECHO, US AIRS, and RCRA NonGen / NLR databases. The site was identified as a historic generator. The potential for storage of hazardous chemicals and the potential for unreported releases exists.	None	NFAATT

CENTRAL ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
11	Exelis Inc./Blatek Inc.	176 Technology Drive	<p>The site was identified on the ECHO, RCRA-SQG, FINDS, and PFAS ECHO databases and waste types included lead, and TCE.</p> <p>The site was identified as a concrete block factory in 1970.</p> <p>The site was observed to be a large commercial machine shop and has the potential for storage of hazardous chemicals and the potential for unreported releases.</p>	Cut, fill, stormwater basin, roadway and RROW along the northern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
	Sound Technology Inc.	171 Technology Drive	<p>The site was identified on the RCRA NonGen / NLR, MANIFEST, FINDS, and ECHO databases; as well as a Captive Hazardous Waste Facility that is inactive and in compliance.</p>		
12	PennDOT Maintenance Yard	1255 Boal Avenue	<p>The site was observed to be a maintenance storage yard with an AST and has the potential for storage of hazardous chemicals and the potential for unreported releases.</p>	Cut, fill, roadway, and RROW along the southern portion of the site; portion of a stormwater basin on the southwestern corner of the site	Initiate Phase I ESA and possibly Phase II/III ESA
13	Harris Township Maintenance Facility	325 Discovery Drive	<p>ASTs and a maintenance garage were observed on the site with the potential for storage of hazardous chemicals and the potential of unreported releases.</p>	Cut, fill, roadway and RROW along the northern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
14	Brick and Stone Supply	409 Discovery Drive	<p>The site was occupied by a masonry contractor with the potential for storage of hazardous chemicals and the potential for unreported releases. The previous site uses are unknown.</p>	Cut, fill, RROW along the northern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA



CENTRAL ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
15	Energycap, Inc.	360 Discovery Drive	A large commercial structure was observed on the site with the potential for storage of hazardous chemicals and the potential for unreported releases. Previous uses are unknown.	None	NFAATT
16	DTC Logistics Inc. (accident)	US 322	The release associated with the accident was identified as having impacted soils and was active and not in compliance due to lack of paperwork documenting compliance.	Cut, fill and roadway	Initiate Phase I ESA and possibly Phase II/III ESA
17	Tait Farm	179 Tait Road	The site was observed to be a tree farm with the potential for herbicide and pesticide application.	Cut and RROW along the northern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
18	Kuhn Farm	2112 Boal Avenue	The site was observed to be a tree farm with the potential for herbicide and pesticide application.	Cut, fill, roadway, and RROW along the northeastern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
19	Oelbermann Farm	North side of Boal Avenue	The site was identified as having impacted soils and was listed as inactive and in compliance. Information provided by the PA DEP indicated that tank closure was accepted. The former tanks were not located in an area with proposed construction.	Cut, fill, roadway and stormwater basins in the central portion of the site	NFAATT
21	XPR Freight LLC (accident)	US 322	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance.	Cut, fill and roadway	Initiate Phase I ESA and possibly Phase II/III ESA
22	BS Transportation of Illinois (accident)	Intersection of Bamboo Lane and US 322 East	The release associated with the accident was identified as having impacted groundwater and soils and was listed as active with continued groundwater monitoring.	None	NFAATT

CENTRAL ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
23	Valley Truck and Trailer Sales and Service, Inc. (accident)	US 322	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. Interviews with PA DEP reported this case as closed.	None	NFA
26	Wheatfield Nursery	1948 General Potter Highway	The site was a commercial nursery with the potential for use and storage of hazardous chemicals and the potential of unreported releases.	Stormwater basin and RROW on the southwestern corner of the site	Initiate Phase I ESA and possibly Phase II/III ESA
28	Land Pro Equipment/John Deer Equipment	110 Summer Lane	The site was observed to be a retail sales and service operation for landscaping equipment and tractors with the potential for storage of hazardous chemicals and the potential for unreported releases.	None	NFAATT
33	Jaybird Manufacturing Inc.	110 Maple Drive	The site was operating as a manufacturer of centrifugal atomizers with the potential for storage of hazardous chemicals and the potential for unreported releases.	None	NFAATT
37	Dumping	Southeast of Tussey View Lane	Dumping of cans, bottles, tires, and other municipal waste were observed.	Cut, fill and roadway	Initiate Phase I ESA and possibly Phase II/III ESA
40	Neff Farm	Off General Potter Highway	The site was identified on the SWF / LF database as a municipal waste operation.	None	NFAATT
46	Renninger Lumber Truck Spill - Charles Rishel Residence	2413 General Potter Highway	The site was identified as having impacted soils, and remediation was performed using the SHS. A potential filling station was identified in 1941.	None	NFAATT

CENTRAL ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
47	Pets Come First	2451 General Potter Highway	The site was identified as a former filling station in 1941 and has the potential for former USTs and use of petroleum products and hazardous chemicals, as well as unreported releases.	None	NFAATT
48	Cowhers Auto Body	RD Box 272A / 114 Cider Press Road	The site was identified on the RCRA-SQG database and previous uses indicated automotive related operations. The use of petroleum products and hazardous chemicals, as well as unreported releases exists.	None	NFAATT
49	RD Greenland and Son Masonry (release)	2606 General Potter Highway	A heating oil release to the surface from an AST was reported as well as an associated water contamination complaint.	Cut, fill, roadway, and RROW	Initiate Phase I ESA and possibly Phase II/III ESA
50	Wolfs Furniture Enterprises (accident)	Route 144 / US 322 near 2606 General Potter Highway	The release associated with the accident was identified as having impacted soils and remediation was performed under the SHS.	Cut and fill along the southern side of the US 322	NFA
52	PTH Express (accident)	US 322 Westbound	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. The PA DEP reported this case was closed.	Cut along the southern side of US 322	NFA
53	Cole Transportation	103 Skyview Drive	The site was identified as having one 10,000-gallon diesel fuel tank. The site was a bus depot with automotive garages with the potential for storage of hazardous chemicals and the potential for unreported releases.	Cut, fill, roadway and RROW	Initiate Phase I ESA and possibly Phase II/III ESA



CENTRAL ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
54	Bingman Lumber (accident)	Skyview Drive	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. The PA DEP reported this case was closed.	Cut, fill and roadway along north and south sides of US 322	NFA
55	322 Potters Mills APR Project, PennDOT Engineering District 2-0	Potters Mills	The site was identified as having impacted groundwater and the potential for pyritic rock being exposed. A filling station was identified in this area in 1941 and 1962.	Cut, fill, roadway and stormwater basin	Initiate Phase I ESA and possibly Phase II/III ESA



SOUTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
1	K & B Logistics (accident)	US 322	The release associated with the accident was identified as having impacted soils. Confirmatory soil samples indicated that all compounds were below the SHS.	Cut, fill, roadway	NFA
2	Former Boalsburg Exxon 92608	US 322 and SR 45	The site was identified on the AUL and LUST databases. The AUL restricts the use of shallow groundwater for potable water supply or agricultural purposes. Previous uses included a gas station (State Gas and Oil Company) and a concrete fuel island in 1970.	None	NFAATT
	Boalsburg Car Company	334 Boal Avenue	The site appeared to operate as an automotive repair facility and used car lot with the potential for storage of hazardous chemicals and the potential of unreported releases.		
3	Automotive repair garage and used car lot	400 Boal Avenue	Groundwater monitoring wells were located on the western portion of the site. The site appeared to operate as an automotive repair garage and used car lot with the potential for storage of hazardous chemicals and the potential of unreported releases.	None	NFAATT
4	Happy Valley Refreshment/Car Wash	420 Boal Avenue	The potential for UST(s) associated with the car wash exists. Previous uses are unknown.	None	NFAATT
5	Wash World Car Wash	426 Boal Avenue	The potential for UST(s) associated with the car wash exists. Previous uses are unknown.	None	NFAATT



SOUTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
6	Shawley Port-a-Potty and Tanks	618 Earlystown Road	A large garage and tanker truck storage/parking area was observed and there is the potential for storage of hazardous chemicals and the potential of unreported releases.	Cut, fill and RROW along the western portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
8	Bolus Freight Systems Inc. (diesel release)	US 322 and SR 45	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. Confirmatory soil samples indicated that all compounds were below the SHS.	Cut, fill and roadway	NFA
9	Prima Express Inc. (accident)	US 322 and SR 45	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. Contamination may still be present.	Cut, fill and roadway	Initiate Phase I ESA and possibly Phase II/III ESA
10	Paradise Datacom Inc. / Boalsburg Plant Locus Inc.	1012 East Boal Avenue	The site was identified on the AIRS databases and as an Air Emissions Plant. The facility manufactures radio and television broadcasting and wireless communication equipment. The site was identified on the FINDS, ECHO, PFAS ECHO, US AIRS, and RCRA NonGen / NLR databases. The site was identified as a historic generator. The potential for storage of hazardous chemicals and the potential for unreported releases exists.	None	NFAATT



SOUTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
11	Exelis Inc./Blatek Inc.	176 Technology Drive	<p>The site was identified on the ECHO, RCRA-SQG, FINDS, and PFAS ECHO databases, and the waste types included lead, and TCE.</p> <p>The site was identified as a concrete block factory in 1970.</p> <p>The site was observed to be a large commercial machine shop and has the potential for storage of hazardous chemicals and the potential for unreported releases.</p>	Cut, fill, roadway, stormwater basin and RROW along the northern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
	Sound Technology Inc.	171 Technology Drive	<p>The site was identified on the RCRA NonGen / NLR, and MANIFEST, FINDS, and ECHO databases.</p> <p>The site was identified as a Captive Hazardous Waste Facility that is inactive and in compliance.</p>		
12	PennDOT Maintenance Yard	1255 Boal Avenue	<p>The site was observed to be a maintenance storage yard with an AST and has the potential for storage of hazardous chemicals and the potential for unreported releases.</p>	Cut, fill, roadway, and RROW along the southern portion of the site; and a portion of a stormwater basin on the southwestern corner of the site	Initiate Phase I ESA and possibly Phase II/III ESA
13	Harris Township Maintenance Facility	325 Discovery Drive	<p>ASTs and a maintenance garage were observed on the site with the potential for storage of hazardous chemicals and the potential of unreported releases.</p>	Cut, fill, roadway and RROW along the northern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA



SOUTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
14	Brick and Stone Supply	409 Discovery Drive	The site was occupied by a masonry contractor with the potential for storage of hazardous chemicals and the potential for unreported releases. The previous site uses are unknown.	Cut, fill, RROW along the northern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
15	Energycap, Inc.	360 Discovery Drive	A large commercial structure was observed on the site with the potential for storage of hazardous chemicals and the potential for unreported releases. Previous uses are unknown.	None	NFAATT
16	DTC Logistics Inc. (accident)	US 322	The release associated with the accident was identified as having impacted soils and was active and not in compliance due to lack of paperwork documenting compliance.	Cut, fill and roadway	Initiate Phase I ESA and possibly Phase II/III ESA
17	Tait Farm	179 Tait Road	The site was observed to be a tree farm with the potential for herbicide and pesticide application.	Cut and RROW along the northern portion of the site	Initiate Phase I ESA and possibly Phase II/III ESA
20	Nittany Grove Mobile Home Park Sewage System/Water System	Timberwood Trail	The site was identified on the FINDS, ECHO, and ICIS databases, as well as on the PA DEP eMapPA as an Envirofacts facility. A pump house was observed along Boal Avenue.	None	NFAATT
	Fegert Property Release	--	The site was identified on the PA DEP ESA Search Tool website as a Land Recycling Cleanup location for soils.		
	Nittany Grove Condo	204 Timberwood Trail	The site was identified on the ECHO and FINDS databases.		

SOUTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
28	Land Pro Equipment/John Deer Equipment	110 Summer Lane	The site was observed to be a retail sales and service operation for landscaping equipment and tractors with the potential for storage of hazardous chemicals and the potential for unreported releases.	None	NFAATT
37	Dumping	Southeast of Tussey View Lane	Dumping of cans, bottles, tires, and other municipal waste was observed.	Cut, fill and roadway	Initiate Phase I ESA and possibly Phase II/III ESA
40	Neff Farm	Off General Potter Highway	The site was identified on the SWF / LF database as a municipal waste operation.	None	NFAATT
46	Renninger Lumber Truck Spill - Charles Rishel Residence	2413 General Potter Highway	The site was identified as having impacted soils, and remediation was performed using the SHS. A potential filling station was identified in 1941.	None	NFAATT
47	Pets Come First	2451 General Potter Highway	The site was identified as a former filling station in 1941 and has the potential for former USTs and use of petroleum products and hazardous chemicals, as well as unreported releases.	None	NFAATT
48	Cowhers Auto Body	RD Box 272A / 114 Cider Press Road	The site was identified on the RCRA-SQG database and previous uses indicated automotive related operations. The use of petroleum products and hazardous chemicals, as well as unreported releases exists.	None	NFAATT
49	RD Greenland and Son Masonry (release)	2606 General Potter Highway	A heating oil release to the surface from an AST was reported as well as an associated water contamination complaint.	Cut, fill, roadway, and RROW	Initiate Phase I ESA and possibly Phase II/III ESA

SOUTH ALTERNATIVE POTENTIAL WASTE SITE RECOMMENDATIONS

WASTE SITE NO.	FACILITY NAME	ADDRESS	CONCERNS	IMPACTS	RECOMMENDATIONS
50	Wolfs Furniture Enterprises (accident)	Route 144 / US 322 near 2606 General Potter Highway	The release associated with the accident was identified as having impacted soils, and remediation was performed under the SHS.	Cut and fill along the southern side of the US 322	NFA
52	PTH Express (accident)	US 322 Westbound	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. The PA DEP reported this case was closed.	Cut along the southern side of US 322	NFA
53	Cole Transportation	103 Skyview Drive	The site was identified as having one 10,000-gallon diesel fuel tank. The site was a bus depot with automotive garages with the potential for storage of hazardous chemicals and the potential for unreported releases.	Cut, fill, roadway and RROW	Initiate Phase I ESA and possibly Phase II/III ESA
54	Bingman Lumber (accident)	Skyview Drive	The release associated with the accident was identified as having impacted soils and was listed as inactive and in compliance. The PA DEP reported this case was closed.	Cut, fill and roadway along north and south sides of US 322	NFA
55	322 Potters Mills APR Project, PennDOT Engineering District 2-0	Potters Mills	The site was identified as having impacted groundwater and the potential for pyritic rock being exposed. A filling station was identified in this area in 1941 and 1962.	Cut, fill, roadway and stormwater basin	Initiate Phase I ESA and possibly Phase II/III ESA



LEGEND

AST – Aboveground Storage Tank

ATV – All Terrain Vehicle

AUL – Activity and Use Limitation

ECHO – Environmental Compliance History Online

ESA – Environmental Site Assessment

FINDS – Facility Index System

LUST – Leaking Underground Storage Tank

MANIFEST – Manifest Information

MW – Monitoring well

NFA – No Further Action

NFAATT – No Further Action at This Time

PA DEP – The Pennsylvania Department of Environmental Protection

PFAS ECHO – Perfluoroalkyl or Polyfluoroalkyl Substances ECHO

RCRA-SQG – Resource Conservation and Recovery Act – Small Quantity Generator

RCRA NonGen / NLR - Resource Conservation and Recovery Act Non-Generators/No Longer Regulated

RRROW – Required Right-of-Way

SHS – Statewide Health Standard

SWF/LF – Solid Waste Facility/Landfill

TCE – Trichloroethylene

US AIRS – Aerometric Information Retrieval System Facility Subsystem

UST – Underground Storage Tank

VCP – Voluntary Cleanup Program